

Work Order ID 109014

Wednesday, November 06, 2013 3:57:31 PM

109014

Page 1

Item ID: D3043-041

Accept

N900040100

Setup

Start

NS1

Revision ID:

Item Name: Step Weldment LH

Stop

NS2

Start Date: 11/1/2013 Start Qty: 2.00

2

Required Date: 11/4/2013 Req'd Qty: 2.00

2Reference: RMA RA111633 *RETURN*

Cust Item ID:

Customer: CAGUS02

Approvals: Process Plan: *MNF.*Date: *13-11-06* Tooling:

Date:

NR1

QC:

Date: SPC (Y/N):

Date:

NR2

Sequence ID/ Work Center ID	Operation Description	Set Up/ Run Hours	Tool ID	Tool #	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
--------------------------------	--------------------------	----------------------	---------	--------	--------------	---------------	---------------	------------------	----------------

Draw Nbr	Revision Nbr
----------	--------------

D3043	Rev A
-------	-------

100	0.00
-----	------

100

QC

Quality Control

Memo 0.00

INSPECT RA 111633 D3043-041 X 2 B107482

STEPS NEED TOUCH UPS

ID AND STOCK UNDER NEW BATCH NUMBER

110

110

Powdercoat

Powder Coating

White Gloss(Ref.4.3.5.1) per OSI005 4.3-Alum

Memo

N/A	0.00
0.05	0.00

2

W.W. 13-11-12

Work Order ID 109014

Wednesday, November 06, 2013 3:57:31 PM

109014

Page 2

Item ID: D3043-041

Accept

Revision ID:

Item Name: Step Weldment LH

Start Date: 11/1/2013 Start Qty: 2.00

2

Required Date: 11/4/2013 Req'd Qty: 2.00

2

Reference: RMA RA111633

Approvals: Process Plan:

Date: Tooling:

Date:

Run Start ***NR1***

QC:

Date: SPC (Y/N):

Date:

Stop ***NR2***Sequence ID/
Work Center IDOperation
DescriptionSet Up/
Run Hours

Tool ID

Tool #

Plan
CodeAccept
QtyReject
QtyReject
NumberInsp.
Stamp

120

120

QC

Quality Control

Memo

0.00

SMB

J

0.00

13/11/13

130

130

Packaging

Packaging

Identify as per dwg & Stock Location:

0.00

PP110918

DAS

32

9-89

13/11/13 (2)

Memo

0.00

ensure old batch number is removed from steps

140

140

QC

Quality Control

QC21- Final Inspection - Work Order Release

0.00

Memo

0.00

13/11/14 (8)

MF

13-11-13

Picklist Print

Wednesday, November 06, 2013 3:57:24 P

Page 1

Work Order ID: 109014

Parent Item: D3043-041

Parent Item Name: Step Weldment LH

Start Date: 11/1/2013

Required Date: 11/4/2013

Start Qty: 2.00

Required Qty: 2.00

Comments: IPP Rev :A New Issue JLM 05-11-01

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
D3043-041		Manufactured	No				Each	0.0000		2			
Step Weldment LH													

2 X 101482
MF
13.11-0-0

BYA

RA 111633 D3043-041

B107482

Received @ Dart Oct 21st, 2013
Inspected @ Dart Oct 31st, 2013

CUSTOMER: AGUSTA WESTLAND
CUSTOMER CONTACT: PATRICK RALSTON
SHIPPED FROM: PHILADELPHIA PENNSYLVANIA
USA

Instructions for RA 111633 D3043-041 B107482

WFT

- Steps are ~~RIGHT~~ HAND's
- Need touch ups as required
- Needs all original B & P/N's removed
- Needs new work order for restocking
- Needs to be re-identified under new B# - *Revert*

Time Estimate = 1 HOURS

Departments Required: Stores

Pictures Attached = NO *44*

QTY INSPECTED = x2 D3043-041 (RH) B107482

**THIS INSTRUCTION SHEET MUST
BE ATTACHED TO THE
RESTOCKING WORK ORDER AT
ALL TIMES!!!**